

Grounding Clamp

Model G-50: Heavy Duty
Ground Clamp, 600 Amp,
Screw Connection: 1/2 - 13
for 3/0 cable

Model RBG-1500: Heavy
Duty Frog Clamp, 1500
Amp, Screw Connection:
1/2 - 13 for 4/0 cable

Order #: G50-WDF (G-50)

Order #: RBG1500-9WDF

